		1986 Porsche 951 Service highlights - WP0AA0956GN155732		
DATE	**MILEAGE**	**DESCRIPTION**	**COST**	
12/17/2018	66,801.00	Replaced fuel pump and line	$ 1,612.25	
11/28/2017	66,723.00	Replaced power steering pump, oil change, diag blown fuse	$ 1,052.25	
4/1/2009	65,723.00	Replace clutch slave and master, new fluid	$ 902.76	
10/2/2003	62,624.00	Adjust tension on TB and shaft belts. R&R pressure line on power steering rack	468.63	
12/31/2002	60,980.00	fuel dampner, regulator and filter replaced	$ 714.13	
11/8/2001	59,180.00	Axel seal repair and refill transmission	$ 481.17	
10/29/2001	58,888.00	lube oil and filter.replace motor mount and seal diff	$ 219.77	
3/29/2001	56,904.00	oil and filter, brake clean	$ 601.22	
7/28/2000	53,600.00	oil and filter, adjust timing belt tension, replace p/s and a/c belt	$ 612.01	
6/28/2000	52,976.00	replace brake pads and rotors	$ 511.94	
5/17/2000	52,000.00	Replace timing belt and water pump	$ 1,959.00	
4/12/1999	46,251.00	reapir leak at power steering resevoir	$ 765.70	
3/16/1994	38,320.00	replace sunroof micro switch	$ 56.16	
6/3/1993	35,473.00	oil and filter, adjust hand brake	$ 142.84	
1/6/1993	31,312.00	timing belt, balance shaft belt, idler pulley	$ 599.55	
1/1/2291	22,876.00	oil and filter, replaced hood struts	$ 333.12	
12/12/1989	20,629.00	replaced oil check valve and pressure switch	$ 986.31	
11/21/1989	20,101.00	Replaced motor mounts and oil presdsure switch	$ 335.00	