



**1257 John Fitch Blvd.
Unit #12
South Windsor, CT 06074**

Estimate

Phone #	Date	Estimate #
860 758 7644	11/5/2021	10030

Name / Address / Phone / Email

Tech	Rep
	DKD

Vehicle Year/Make/Model	VIN	License Plate #	Mileage @ Last Service
1995 Nissan 300ZX	JN1CZ24D0SX570489	283HCV	38886

Description	Qty	Cost	Total:
Labor - Compression Test - Results: Cyl #1: , Cyl #2: , Cyl #3: , Cyl #4: , Cyl #5: , Cyl#6 - Spark Plug Gap - Oil Condition: - Coolant Condition: - Tire Pressure: - Boost Leaks Diagnostic Labor \$175.00/Hr. Inspect car carefully and compile list of anything that looks as it may need replacement after many years of sitting.	1	450.00	450.00T
	1	175.00	175.00T

I voluntarily request that repairs be performed on my vehicle without an advanced estimate of their cost. By signing this form, I authorize reasonable and necessary costs to remedy the problems complained of up to a maximum of \$ _____. The Repair shop may not exceed this amount without my written or oral consent.

Would you like your stock parts back? ☐ Yes ☐ No

I hereby authorize the above repair work to be done along with the necessary materials. ECS and ECS' employees may operate the vehicle for purposes of testing, inspection, or delivery at my risk. An express mechanics lien is acknowledged on the above vehicle to secure the amount of repairs thereto. As a courtesy, ECS will allow up to 5 consecutive days after the completion of the vehicle, before storage rates will apply. It is understood that ECS will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond ECS' control. Furthermore, it is understood that aftermarket performance parts may void the original manufactures warranty in part or its entirety, and that ECS will not be held responsible should the vehicles warranty be voided as a result of ECS installing such parts. All aftermarket parts are for OFF ROAD USE ONLY! And are being installed and used at your own risk.

Total:

--

Customer Signature



**1257 John Fitch Blvd.
Unit #12
South Windsor, CT 06074**

Estimate

Phone #	Date	Estimate #
860 758 7644	11/5/2021	10030

Name / Address / Phone / Email

Tech	Rep
	DKD

Vehicle Year/Make/Model	VIN	License Plate #	Mileage @ Last Service
1995 Nissan 300ZX	JN1CZ24D0SX570489	283HCV	38886
Description	Qty	Cost	Total:
Hand Wash and Dry Clean & Dress Wheels and Tires Clay bar/ Paint Decontamination 2 Step Compound/Finishing Polish on Exterior Paint Apply Sealant & Wax on Exterior Paint + Engine Bay Cleaned and Dressed Full Interior Including Carpets and Upholstery Shampooed Chrome Exhaust Tips Cleaned and Polished Exterior Plastics Cleaned and Dressed Glass and Door Jambes Cleaned Apply Leather Conditioner Meguiar's Air Refresher - New Car Scent	1	525.00	525.00T
Environmental Waste Disposal and State Fee CT Sales Tax - 6.35%	1	14.46 10.00 6.35%	14.46T 10.00 73.94

I voluntarily request that repairs be performed on my vehicle without an advanced estimate of their cost. By signing this form, I authorize reasonable and necessary costs to remedy the problems complained of up to a maximum of \$ _____. The Repair shop may not exceed this amount without my written or oral consent.

Would you like your stock parts back? ☐ Yes ☐ No

I hereby authorize the above repair work to be done along with the necessary materials. ECS and ECS' employees may operate the vehicle for purposes of testing, inspection, or delivery at my risk. An express mechanics lien is acknowledged on the above vehicle to secure the amount of repairs thereto. As a courtesy, ECS will allow up to 5 consecutive days after the completion of the vehicle, before storage rates will apply. It is understood that ECS will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond ECS' control. Furthermore, it is understood that aftermarket performance parts may void the original manufactures warranty in part or its entirety, and that ECS will not be held responsible should the vehicles warranty be voided as a result of ECS installing such parts. All aftermarket parts are for OFF ROAD USE ONLY! And are being installed and used at your own risk.

Total: \$1,248.40

--

Customer Signature _____



Invoice

**1257 John Fitch Blvd.
Unit #12
South Windsor, CT 06074**

Phone #	Date	Invoice #
860 758 7644	11/11/2021	10210
sales@ecs-performance.com		

Bill To

Tech	Rep
	DKD

Vehicle Year/Make/Model	VIN	License Plate #	Mileage @ Last Service
1995 Nissan 300ZX	JN1CZ24D0SX570489	283HCV	38886
Description	Quantity	Rate	Amount
Parts NGK 5464 Spark Plugs Laser Iridium	4	13.06	52.24T
Labor - Compression Test - Results: Cyl #1: 155 , Cyl #2: 145 , Cyl #3: 148 , Cyl #4: 145 , Cyl #5: 149 , Cyl#6: 145 - Spark Plug Gap: cyl 1: .042/.04, cyl 2: .044/.04, cyl 3 .045/.04, cyl 4 .045/.04, cyl 5 .045/.04, cyl 6, .045/.04 - Oil Condition: full/mid brown - Coolant Condition: full/green - Boost Leaks: none present Diagnostic Labor \$175.00/Hr. Inspect car carefully and compile list of anything that looks as it may need replacement after many years of sitting.	1	450.00	450.00T
Environmental Waste Disposal and State Fee	1	175.00	175.00T
		10.00	10.00
ECS Performance warranties labor for a period of 30 days from the invoice date. All parts are covered under specific manufacturers warranty. Aftermarket performance parts may void the original manufactures warranty in part or in its entirety, ECS will not be held responsible should the vehicle warranty be voided. As a courtesy, ECS will allow up to 10 consecutive days after the completion of the vehicle, before storage rates will apply. All aftermarket parts are for OFF ROAD USE ONLY! And are being installed and used at your own risk. Please contact ECS Performance should you have any questions. (860) 758 7644		Sales Tax (6.35%)	
Page 1		Total	
		Balance Due	



Invoice

**1257 John Fitch Blvd.
Unit #12
South Windsor, CT 06074**

Phone #	Date	Invoice #
860 758 7644	11/11/2021	10210
sales@ecs-performance.com		

Bill To

Tech	Rep
	DKD

Vehicle Year/Make/Model	VIN	License Plate #	Mileage @ Last Service
1995 Nissan 300ZX	JN1CZ24D0SX570489	283HCV	38886

Description	Quantity	Rate	Amount
<p>***Notes***</p> <p>Car needs new tires all around as well as new pads and rotors. Some vibration when driving that we feel new tires and brakes will resolve. Once new tires on, 4 corner alignment also recommended.</p> <p>Tire sizes: Rear 275/35/19, front 235/40/17</p> <p>Oil doesn't look to be in too bad of condition but if more than a few years old we recommend an oil change.</p> <p>Brake fluid is also past expiration date and needs changing.</p> <p>During test drive tech noted that he hears a slight squeak noise coming from the transmission. He believes it is likely the throwout bearing in the clutch making the noise. Clutch replacement not necessary but may resolve squeak.</p> <p>Overall the car is in very good condition for it's age. Engine hoses appear to all still be squishy and not dry rotted. Suspension bushings and components also look surprisingly good for their age.</p>			

ECS Performance warranties labor for a period of 30 days from the invoice date. All parts are covered under specific manufacturers warranty. Aftermarket performance parts may void the original manufactures warranty in part or in its entirety, ECS will not be held responsible should the vehicle warranty be voided. As a courtesy, ECS will allow up to 10 consecutive days after the completion of the vehicle, before storage rates will apply. All aftermarket parts are for OFF ROAD USE ONLY! And are being installed and used at your own risk. Please contact ECS Performance should you have any questions. (860) 758 7644

Sales Tax (6.35%) \$43.00

Total \$730.24

Balance Due \$730.24



**1257 John Fitch Blvd.
Unit #12
South Windsor, CT 06074**

Estimate

Phone #	Date	Estimate #
860 758 7644	11/16/2021	10040

Name / Address / Phone / Email

Tech	Rep
	DKD

Vehicle Year/Make/Model	VIN	License Plate #	Mileage @ Last Service
1995 Nissan 300ZX	JN1CZ24D0SX570489	283HCV	38886
Description	Qty	Cost	Total:
Parts & Supplies			
Falken Azenis FK510	2	253.00	506.00T
275/35ZR19 28034137			
Falken Azenis FK510	2	159.00	318.00T
245/40ZR17 28032997			
Power Stop 89-96 Nissan 300ZX Front & Rear Z26 Street Warrior Brake Kit	1	643.72	643.72T
K2754-26			
1 x psbK666-26 Power Stop 89-96 Nissan 300ZX Rear Z26 Street Warrior Brake Kit			
1 x psbK3100-26 Power Stop 89-96 Nissan 300ZX Front Z26 Street Warrior Brake Kit			
Shipping Charges for Parts Ordered	1	39.99	39.99
Brake Fluid - Valvoline - 32 oz. DOT 3/4	2	15.88	31.76T
South Bend / DXD Racing Clutch 90-96 Nissan 300ZX Turbo 3.0L Stg 2 Daily Clutch Kit	1	549.61	549.61T
K06046-HD-O			
Labor			
Mount & Road Force Balance New Tires	1	199.99	199.99T
Oil and Filter Change with Valvoline Motor Oil 10W30 Full Synthetic & New Filter	1	175.00	175.00T

I voluntarily request that repairs be performed on my vehicle without an advanced estimate of their cost. By signing this form, I authorize reasonable and necessary costs to remedy the problems complained of up to a maximum of \$ _____. The Repair shop may not exceed this amount without my written or oral consent.

Would you like your stock parts back? ☐ Yes ☐ No

I hereby authorize the above repair work to be done along with the necessary materials. ECS and ECS' employees may operate the vehicle for purposes of testing, inspection, or delivery at my risk. An express mechanics lien is acknowledged on the above vehicle to secure the amount of repairs thereto. As a courtesy, ECS will allow up to 5 consecutive days after the completion of the vehicle, before storage rates will apply. It is understood that ECS will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond ECS' control. Furthermore, it is understood that aftermarket performance parts may void the original manufactures warranty in part or its entirety, and that ECS will not be held responsible should the vehicles warranty be voided as a result of ECS installing such parts. All aftermarket parts are for OFF ROAD USE ONLY! And are being installed and used at your own risk.

Total:

--

Customer Signature



**1257 John Fitch Blvd.
Unit #12
South Windsor, CT 06074**

Estimate

Phone #	Date	Estimate #
860 758 7644	11/16/2021	10040

Name / Address / Phone / Email

Tech	Rep
	DKD

Vehicle Year/Make/Model	VIN	License Plate #	Mileage @ Last Service
1995 Nissan 300ZX	JN1CZ24D0SX570489	283HCV	38886
Description	Qty	Cost	Total:
Mechanical Labor \$175/hr. Installation of ECS supplied Product: Brake Fluid Flush	1	175.00	175.00T
Subcontracted Work: Flywheel Resurfacing	1	150.00	150.00T
Mechanical Labor \$175/hr. Installation of ECS supplied Product: Clutch & resurfaced flywheel	6	175.00	1,050.00T
Environmental Waste Disposal and State Fee	1	10.00	10.00
CT Sales Tax - 6.35%		6.35%	241.24

I voluntarily request that repairs be performed on my vehicle without an advanced estimate of their cost. By signing this form, I authorize reasonable and necessary costs to remedy the problems complained of up to a maximum of \$ _____. The Repair shop may not exceed this amount without my written or oral consent.

Would you like your stock parts back? ☐ Yes ☐ No

I hereby authorize the above repair work to be done along with the necessary materials. ECS and ECS' employees may operate the vehicle for purposes of testing, inspection, or delivery at my risk. An express mechanics lien is acknowledged on the above vehicle to secure the amount of repairs thereto. As a courtesy, ECS will allow up to 5 consecutive days after the completion of the vehicle, before storage rates will apply. It is understood that ECS will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond ECS' control. Furthermore, it is understood that aftermarket performance parts may void the original manufactures warranty in part or its entirety, and that ECS will not be held responsible should the vehicles warranty be voided as a result of ECS installing such parts. All aftermarket parts are for OFF ROAD USE ONLY! And are being installed and used at your own risk.

Total: \$4,090.31

--

Customer Signature _____



**1257 John Fitch Blvd
Unit #12
South Windsor, CT 06074**

Estimate

Phone #	Date	Estimate #
860 758 7644	5/27/2022	10339

Name / Address / Phone / Email

Tech	Rep
Seth/CSP	DKD

Vehicle Year/Make/Model	VIN	License Plate #	Mileage @ Last Service
1995 Nissan 300ZX	JN1CZ24D0SX570489	283HCV	38886
Description	Qty	Cost	Total:
Parts & Supplies			
Z1 Motorsports Replacement A/C Amplifier	1	99.00	99.00T
Z1 Motorsports	1	265.00	265.00T
1x OEM 300ZX (Z32) 4"x6" Non-Bose Rear Speaker Brackets			
1x OEM 300ZX (Z32) Rear Speaker Cover Grille - Non BOSE - Side: Driver			
1x OEM 300ZX (Z32) Rear Speaker Cover Grille - Non BOSE - Side: Passenger			
Z1 Motorsports	1	75.00	75.00T
Used 300ZX Blower Motor w/ Wheel			
6 1/2" 6.5" Rear Speaker Adapters - SAK044_55-1 Pair	1	24.99	24.99T
6 1/2" Speakers to work with non-BOSE setup x2	1	99.00	99.00T
Labor			
Mechanical Labor \$175/hr. Installation of ECS supplied Product: Install replacement blower motor, A/C Amp, & speaker conversion Includes interior & exterior detailing packages. (includes removal and install of interior for deep cleaning)	2	175.00	350.00T
	1	500.00	500.00T
Environmental Waste Disposal and State Fee	1	10.00	10.00
CT Sales Tax - 6.35%		6.35%	89.72

I voluntarily request that repairs be performed on my vehicle without an advanced estimate of their cost. By signing this form, I authorize reasonable and necessary costs to remedy the problems complained of up to a maximum of \$ _____. The Repair shop may not exceed this amount without my written or oral consent.

Would you like your stock parts back? ☐ Yes ☐ No

I hereby authorize the above repair work to be done along with the necessary materials. ECS and ECS' employees may operate the vehicle for purposes of testing, inspection, or delivery at my risk. An express mechanics lien is acknowledged on the above vehicle to secure the amount of repairs thereto. As a courtesy, ECS will allow up to 5 consecutive days after the completion of the vehicle, before storage rates will apply. It is understood that ECS will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond ECS' control. Furthermore, it is understood that aftermarket performance parts may void the original manufactures warranty in part or its entirety, and that ECS will not be held responsible should the vehicles warranty be voided as a result of ECS installing such parts. All aftermarket parts are for OFF ROAD USE ONLY! And are being installed and used at your own risk.

Total: \$1,512.71

Customer Signature _____



Invoice

Unit #12
South Windsor, CT 06074

Phone #	Date	Invoice #
860 758 7644	12/20/2021	10274
sales@ecs-performance.com		

Bill To

Tech	Rep
Seth/CSP	DKD

Vehicle Year/Make/Model	VIN	License Plate #	Mileage @ Last Service
1995 Nissan 300ZX	JN1CZ24D0SX570489	283HCV	38886

Description	Quantity	Rate	Amount
Parts & Supplies			
Falken Azenis FK510 275/35ZR18 28034137	2	253.00	506.00T
Falken Azenis FK510 245/40ZR17 28032997	2	159.00	318.00T
Power Stop 89-96 Nissan 300ZX Front & Rear Z26 Street Warrior Brake Kit K2754-26	1	643.72	643.72T
1 x psbK666-26 Power Stop 89-96 Nissan 300ZX Rear Z26 Street Warrior Brake Kit			
1 x psbK3100-26 Power Stop 89-96 Nissan 300ZX Front Z26 Street Warrior Brake Kit			
Shipping Charges for Parts Ordered	1	39.99	39.99
Brake Fluid - Valvoline - 32 oz. DOT 3/4	2	15.88	31.76T
South Bend / DXD Racing Clutch 90-96 Nissan 300ZX Turbo 3.0L Stg 2 Daily Clutch Kit K06046-HD-O	1	549.61	549.61T
Subtotal of all above items			2,089.08
Labor			
Mount & Road Force Balance New Tires	1	199.99	199.99T
Oil and Filter Change with Valvoline Motor Oil 10W30 Full Synthetic & New Filter	1	175.00	175.00T
Mechanical Labor \$175/hr. Installation of ECS supplied Product: Brake Fluid Flush	1	175.00	175.00T
Subcontracted Work: Flywheel Resurfacing	1	150.00	150.00T
Mechanical Labor \$175/hr. Installation of ECS supplied Product: Clutch & resurfaced flywheel	6	175.00	1,050.00T
Replace Brake Pads/Rotors (one axle, labor only)	2	175.00	350.00T

ECS Performance warranties labor for a period of 30 days from the invoice date. All parts are covered under specific manufacturers warranty. Aftermarket performance parts may void the original manufactures warranty in part or in its entirety, ECS will not be held responsible should the vehicle warranty be voided. As a courtesy, ECS will allow up to 10 consecutive days after the completion of the vehicle, before storage rates will apply. All aftermarket parts are for OFF ROAD USE ONLY! And are being installed and used at your own risk. Please contact ECS Performance should you have any questions. (860) 758 7644

Sales Tax (6.35%)

Total

Balance Due



Invoice

Unit #12
South Windsor, CT 06074

Phone #	Date	Invoice #
860 758 7644	12/20/2021	10274
sales@ecs-performance.com		

Bill To

Tech	Rep
Seth/CSP	DKD

Vehicle Year/Make/Model	VIN	License Plate #	Mileage @ Last Service
1995 Nissan 300ZX	JN1CZ24D0SX570489	283HCV	38886

Description	Quantity	Rate	Amount
Hand Wash and Dry Clean & Dress Wheels and Tires Clay bar/ Paint Decontamination 2 Step Compound/Finishing Polish on Exterior Paint Apply Sealant & Wax on Exterior Paint + Engine Bay Cleaned and Dressed Full Interior Including Carpets and Upholstery Shampooed Chrome Exhaust Tips Cleaned and Polished Exterior Plastics Cleaned and Dressed Glass and Door Jambs Cleaned Apply Leather Conditioner Meguiar's Air Refresher - New Car Scent	1	525.00	525.00T
	1	14.46	14.46T
Environmental Waste Disposal and State Fee	1	10.00	10.00
Tire Disposal Fee	4	5.75	23.00

ECS Performance warranties labor for a period of 30 days from the invoice date. All parts are covered under specific manufacturers warranty. Aftermarket performance parts may void the original manufactures warranty in part or in its entirety, ECS will not be held responsible should the vehicle warranty be voided. As a courtesy, ECS will allow up to 10 consecutive days after the completion of the vehicle, before storage rates will apply. All aftermarket parts are for OFF ROAD USE ONLY! And are being installed and used at your own risk. Please contact ECS Performance should you have any questions. (860) 758 7644

Sales Tax (6.35%) \$297.72

Total \$5,059.25

Balance Due \$2,789.49



Invoice

**1257 John Fitch Blvd
Unit #12
South Windsor, CT 06074**

Phone #	Date	Invoice #
860 758 7644	8/4/2022	10676
sales@ecs-performance.com		

Bill To

Tech	Rep
	DKD

Vehicle Year/Make/Model	VIN	License Plate #	Mileage @ Last Service
1995 Nissan 300ZX	JN1CZ24D0SX570489	283HCV	38886
Description	Quantity	Rate	Amount
Labor Mechanical Labor \$195/Hr. Diag & repair of HVAC system: 6.25 Diag & repair of blend door actuator: 5 Complete PPI & address belts & bulbs: 2 Subcontracted Work: Car photographs for sale listing	13.25 1	195.00 100.00	2,583.75T 100.00T
Supplies Gasoline used in vehicle for testing purposes A/C Belt \$27.88 Power steering belt \$44.04 Alternator belt \$31.96 Map bulb \$3.58 Footlight bulb \$1.54 Environmental Waste Disposal and State Fee	 1	 10.00	 10.00
ECS Performance warranties labor for a period of 30 days from the invoice date. All parts are covered under specific manufacturers warranty. Aftermarket performance parts may void the original manufactures warranty in part or in its entirety, ECS will not be held responsible should the vehicle warranty be voided. As a courtesy, ECS will allow up to 5 consecutive days after the completion of the vehicle, before storage rates will apply. All aftermarket parts are for OFF ROAD USE ONLY! And are being installed and used at your own risk. Please contact ECS Performance should you have any questions. (860) 758 7644		Sales Tax (6.35%)	\$177.34
		Total	\$3,007.08
		Balance Due	\$3,007.08



Invoice

1257 John Fitch Blvd
Unit #12
South Windsor, CT 06074

Phone #	Date	Invoice #
860 758 7644	8/4/2022	10676
sales@ecs-performance.com		

PAID
08/05/2022

Bill To

Tech	Rep
	DKD

Vehicle Year/Make/Model	VIN	License Plate #	Mileage @ Last Service
1995 Nissan 300ZX	JN1CZ24D0SX570489	283HCV	38886

Description	Quantity	Rate	Amount
Labor Mechanical Labor \$195/Hr. Diag & repair of HVAC system: 6.25 Diag & repair of blend door actuator: 5 Complete PPI & address belts & bulbs: 2 Subcontracted Work: Car photographs for sale listing	13.25 1	195.00 100.00	2,583.75T 100.00T
Supplies Gasoline used in vehicle for testing purposes A/C Belt \$27.88 Power steering belt \$44.04 Alternator belt \$31.96 Map bulb \$3.58 Footlight bulb \$1.54	 1 1	 26.99 109.00	 26.99 109.00T
Environmental Waste Disposal and State Fee	1	10.00	10.00

ECS Performance warranties labor for a period of 30 days from the invoice date. All parts are covered under specific manufacturers warranty. Aftermarket performance parts may void the original manufactures warranty in part or in its entirety, ECS will not be held responsible should the vehicle warranty be voided. As a courtesy, ECS will allow up to 5 consecutive days after the completion of the vehicle, before storage rates will apply. All aftermarket parts are for OFF ROAD USE ONLY! And are being installed and used at your own risk. Please contact ECS Performance should you have any questions. (860) 758 7644

Sales Tax (6.35%) \$177.34

Total \$3,007.08

Balance Due \$0.00

INVOICE



Glass House Paint Studios llc
2331 w Hampden ave englewood, co
unit 171-172
7206336317

BILL TO

INVOICE # 2160
INVOICE DATE 07/16/2024

QTY	DESCRIPTION	UNIT PRICE	AMOUNT
10.6	ENGINE BAY -right strut tower r&i cruise control and some sensors/ clips repair and spot in refinish -remove and refinish small brackets -replace hardware(will be in its own line along with suspension hardware)	120.00	1,272.00
11	FRONT SUSPENSION -remove and install subframe and all suspension components -suspend engine and trans	120.00	1,320.00
1	FRONT SUSPENSION -sand blast rough estimate may change	650.00	650.00
8.2	FRONT SUSPENSION -refinsh	120.00	984.00
1	FRONT SUSPENSION remove and replace inner and outer toe rods and sway bar links parts 460 labor 280	740.00	740.00
2.6	EXHAUST remove and install (may need hardware/gaskets)	120.00	312.00
8.4	REAR SUSPENSION remove and install	120.00	1,008.00

1	REAR SUSPENSION blast all components rough estimate, may change	420.00	420.00
7.4	REAR SUSPENSION REFINISH	120.00	888.00
1	REAR SUSPENSION remove and replace inner and outer tie rods and end links	0.00	0.00
1	replacement hardware for whatever needed will address after tear down	0.00	0.00
1	shop supplies and materials	1,650.00	1,650.00
1	complete car paint correction	800.00	800.00
1	ALIGNMENT sublet	250.00	250.00
1	replace all 4 wheels with oem spec llan-cult cars	850.00	850.00
		TOTAL	\$11,144.00

From: Mountainside Mobile Detailing noreply@fieldd.co
Subject: Mountainside Mobile Detailing Booking Invoice
Date: December 10, 2024 at 2:18 PM

MD



Rate your Experience



Tax Invoice

Thanks for choosing Mountainside Mobile Detailing

Invoice Details

Invoice #

JOB1304

Invoice Terms

7 days from issue

Date Invoice Issue

10th Dec 2024


Due Date

17th Dec 2024

Billed To

2331 W Hampden Ave, Sheridan
ilan@cultcarsforsale.com

Job Details



Time

11:00am - 3:00pm Tue Dec 10th '24

Address

2331 W Hampden Ave, Sheridan

Service Description

Engine Bay Detail	\$500.00
-------------------	----------

+	\$0.00
Total	\$500.00

Service Provider

Aaron

Mountainside Mobile Detailing: 92-1534900

Invoice Info

Please settle this invoice within 7 days

Thanks for choosing Mountainside Mobile Detailing. We look forward seeing you again soon!

[Pay Online](#)

Your feedback matters! Show your support by leaving us a Google review.



nick@mountainsidedetail.com
(303) 653-7279

Powered by [fieldd.co](#)

Colorado Performance Specialists

2331 W. Hampden Ave Unit 158

Englewood, CO. 80110

Phone: 720-413-1493 Fax: 000- -

Big Enough to Repair and Small Enough to Care

INVOICE**3739**

Org. Est. # 004993

INVOICE

Printed Date: 11/20/2024

Work Completed: 11/20/2024

1995 Nissan - 300ZX Turbo - 3L, V6 (181CI) VIN(C)

Lic # :

Odometer In : 39808

VIN # : JN1CZ24D0 SX570489

Part Description	/ Number	Qty	Sale	Ext	Labor Description	Ext
Radius arms		2.00	150.00	300.00	Inspection	100.00
xx					AIR CONDITIONING SYSTEM - Complete Charge -	175.00
Timing Belt Kit		1.00	428.45	428.45	[Includes: Air Conditioning system recover, evacuate and recharge.]	
TB 251 K1						
Water Pump		1.00	238.93	238.93	TIMING BELT - Remove & Replace	1,225.00
B1010-22P27					Repair rusted catalyst outlet studs	350.00
T-Belt Tension Assembly w/ Hyd.		1.00	300.29	300.29	Replace both radius arms	175.00
Adjuster					Hazardous Materials	10.00
13070-45V04						
Timing cover hardware with shipping		1.00	92.80	92.80		
xx						
Thermostat (76.5 C/170 F)		1.00	24.30	24.30		
21200-V5010						
Serpentine Belt		1.00	22.34	22.34		
K040398						
Serpentine Belt		1.00	30.12	30.12		
K040378						
Serpentine Belt		1.00	22.20	22.20		
K040365						
Freon		1.50	22.50	33.75		
xx						
Service ports		2.00	10.49	20.98		
xx						
Coolant/Antifreeze (GREEN) 1 Gallon		3.00	28.71	86.13		
GC-C1A04-U-01-01						
Power steering reservoir bolts		3.00	2.47	7.41		
xx						
Shop Supplies				10.00		

Colorado Performance Specialists
2331 W. Hampden Ave Unit 158
Englewood, CO. 80110
Phone: 720-413-1493 Fax: 000- -
Big Enough to Repair and Small Enough to Care

INVOICE

3739

Org. Est. # 004993

INVOICE

Printed Date: 11/20/2024

Work Completed: 11/20/2024

1995 Nissan - 300ZX Turbo - 3L, V6 (181CI) VIN(C)

Lic # :

Odometer In : 39808

VIN # : JN1CZ24D0 SX570489

Part Description	/ Number	Qty	Sale	Ext	Labor Description	Ext
------------------	----------	-----	------	-----	-------------------	-----

Org. Estimate 3,778.07 Revisions 0.00 Current Estimate 3,778.07

Labor:	2,025.00
Parts:	1,617.70
HazMat:	10.00
SubTotal:	3,652.70
Tax:	125.37
Total:	3,778.07
Bal Due:	\$3,778.07

[Payments -]

Vehicle Received: 11/20/2024

Customer Number : 1033

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is 6 month or 6,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Signature _____ Date _____

Visit us on the web: www.cpsdenver.com

Email Address: magrodnia@gmail.com

VIEW SALES INVOICE
DISCOUNT TIRE

9/24/2024
12:37 PM

1995 NISSAN
300ZX
ALL TURBO

COD 17
300 W HAMPDEN AVE
ENGLEWOOD, CO 80110
303.781.6040

Mileage Unknown
Torque Specs: 85

Carry Out W/Vehicle

Salesperson 929
JOSE C

Invoice #
6550608

Estimated Completion Time: 02:16 PM

Article	Qty	Description	FET	Price	Amount
42466	2	245 /45 R16 94W SL BSW		276.00	552.00
NRM		YOK ADVAN A052			
BOLT PATTERN: 5-114.3					
INFLATION R:028					
80017	0	CERTIFICATES FOR		46.97	.00
NRM		REFUND, REPLACEMENT			
80224	2	WASTE TIRE		3.00	6.00
NRM		DISPOSAL FEE			
80219	2	INSTALLATION &		22.00	44.00
NRM		LIFE OF TIRE MAINTENANCE			
Terms and Conditions can be found at					
www.discounttire.com/customer-service/invoice-terms					
42775	2	225 /50 R16 96W XL BSW		221.00	442.00
NRM		YOK ADVAN A052			
INFLATION F:028					
80017	0	CERTIFICATES FOR		41.74	.00
NRM		REFUND, REPLACEMENT			
80224	2	WASTE TIRE		3.00	6.00
NRM		DISPOSAL FEE			
80219	2	INSTALLATION &		22.00	44.00
NRM		LIFE OF TIRE MAINTENANCE			
Terms and Conditions can be found at					
www.discounttire.com/customer-service/invoice-terms					
loose wheel in last bay z wheel staggered					

The tire and/or wheel you have chosen is different from the original equipment provided with your vehicle and may change its handling or stability characteristics.
Further information is available from your Discount Tire salesperson.

Sub Total: 1,094.00

TAX ID:	293810	Sales Tax:	.00	.
		Sales Total:	1,094.00	.
		Tendered:	1,094.00	(AMX)
Tkn#	XXXXXXXXX4003	Tendered Today:	1,094.00	.
Ath#	237588	Tendered Total:	1,094.00	.
				.
				.

INVOICE

**Glass House Paint Studios llc**

2331 w Hampden ave englewood, co
unit 171-172
7206336317

BILL TO**INVOICE #**

2160

INVOICE DATE

07/16/2024

QTY	DESCRIPTION	UNIT PRICE	AMOUNT
10.6	ENGINE BAY -right strut tower r&i cruise control and some sensors/ clips repair and spot in refinish -remove and refinish small brackets -replace hardware(will be in its own line along with suspension hardware)	120.00	1,272.00
11	FRONT SUSPENSION -remove and install subframe and all suspension components -suspend engine and trans	120.00	1,320.00
1	FRONT SUSPENSION -sand blast rough estimate may change	650.00	650.00
8.2	FRONT SUSPENSION -refinsh	120.00	984.00
1	FRONT SUSPENSION remove and replace inner and outer toe rods and sway bar links parts 460 labor 280	740.00	740.00
2.6	EXHAUST remove and install (may need hardware/gaskets)	120.00	312.00
8.4	REAR SUSPENSION remove and install	120.00	1,008.00

1	REAR SUSPENSION blast all components rough estimate, may change	420.00	420.00
7.4	REAR SUSPENSION REFINISH	120.00	888.00
1	REAR SUSPENSION remove and replace inner and outer tie rods and end links	0.00	0.00
1	replacement hardware for whatever needed will address after tear down	0.00	0.00
1	shop supplies and materials	1,650.00	1,650.00
4.2	FRONT BUMPER remove refinish and Install	120.00	504.00
1	complete car paint correction	800.00	800.00
1	ALIGNMENT sublet	250.00	250.00
1	replace all 4 wheels with oem spec llan-cult cars	850.00	850.00
TOTAL			\$11,648.00