



**1982 Nissan 280ZX**  
 1N1CZ04SXCX626281  
 Engine: L6, 2.8L; Turbo  
 Plate:  
 Odometer In: 67175  
 Odometer Out: 67175

**Advisor: Lazaro Pichardo**  
 Technician: J'koi

**GRAND TOTAL: \$2,011.46**

✓ PAID

**SERVICES**

**1 Remove and Replace Tie Rod End** **SUBTOTAL: \$291.08**

**LABOR**

<b>PARTS</b>	<b>QTY</b>
Import Direct Chassis Steering Tie Rod End	2.0

**2 Remove & Replace: Ball Joint** **SUBTOTAL: \$612.84**

**LABOR**

Remove & Replace: BALL JOINT DOES NOT include alignment.

<b>PARTS</b>	<b>QTY</b>
MasterPro Chassis Suspension Ball Joint	1.0
CTR Suspension Ball Joint	1.0

**3 Four Wheel Alignment** **SUBTOTAL: \$99.00**

**LABOR**

Perform alignment adjustments to factory specifications  
 Adjust tire pressures to factory specifications  
 Measure and record pre and post alignment condition  
 Inspect steering and suspension components  
 Center steering wheel; calibrate zero point position (as needed)

<b>HAZMATS &amp; FEES</b>	<b>QTY</b>
---------------------------	------------

**4 Replace 12v Battery** **SUBTOTAL: \$198.50**

**LABOR**

Remove and replace 12v Battery  
 Clean terminal cables

<b>PARTS</b>	<b>QTY</b>
ACDelco Gold Vehicle Battery	1.0

HAZMATS & FEES	QTY
State Disposal Fee - Lead Acid Battery	1.0

## 5 Remove & Replace: Oil Pan Gasket(Labor Only)

**SUBTOTAL: \$658.47**

**LABOR**

Remove & Replace: OIL PAN GASKET

PARTS	QTY
Honda HONDA BOND	1.0

**SUBLETS**

frieght

**Terms of Service:**

1. "YES, DO THIS WORK"  
 I hereby authorize the corresponding service to be done along with the necessary materials and documents such as "Waiver Of Liability" if present and required.
2. We understand that unexpected issues can arise, and we are committed to open communication with our valued customers. If our technicians encounter any unforeseen challenges during the service or repair process, we will promptly inform you of the situation and present a detailed plan to address the issue. Vehicles naturally age, and various parts can become more brittle or degraded over time. Our skilled technicians will exercise the utmost care and professionalism when working on your vehicle. However, due to factors such as the vehicle's age, condition, and prior maintenance history, there is a possibility that certain parts could break or experience increased fragility during the course of necessary service or repairs.
3. "YOU MAY DRIVE MY CAR ON PUBLIC ROADS"  
 The J.A.P. shop staff may operate my vehicle for the purpose of testing, inspection, and delivery.
4. "NO PAYMENT, NO KEYS"  
 An express lien is acknowledged on my vehicle to secure the amount of services thereto.
5. "ONLINE COMMUNICATION OK"  
 I welcome email from The JAP shop as a means of receiving copies of my estimate, work order, and invoice.
6. "OVERNIGHT PARKING"  
 On working vehicles, there would be \$45 charge per night on 3rd day after closing date listed on the invoice and/or \$170 per day after the diagnostic/inspection has been complete on inoperable vehicles.
7. "WARRANTY"  
 We provide 36 months 36,000 miles parts and labor warranty. Warranty does not apply to used or customer supplied parts.
8. "HERE'S MY SIGNATURE"  
 I endorse the attached digital image of my signature as equivalent to my written signature and as proof of my agreement to these five terms.

**GRAND TOTAL: \$2,011.46**

Shop Supplies: \$20.00  
 Sales Tax: \$131.57

**✓ PAID**

10/05/2023 12:56 PM  
 Paid by Check: **\$2,011.46**  
 Notes: "# 7403"

**Authorization:**



**Vertical Automotive**

1100 W Oakland Park Blvd Bay 5, Wilton Manors, FL 33311  
954-565-1518  
contact@verticalautomotive.com

**Invoice #5317**

Page 3 of 4  
09/28/2023

---

**INSPECTION REPORT**

---

**Replace 12v Battery**

<input checked="" type="checkbox"/>	Confirm terminal cable tightness
<input checked="" type="checkbox"/>	Input radio/NAV code as needed
<input checked="" type="checkbox"/>	Reinitialize systems as needed
<input checked="" type="checkbox"/>	Reset clock

**FINDINGS**

**Replace 12v Battery    \$198.50 +tax**


Approved by phone, 11:29am 9/21/23

Written by Reece at 09/21/2023 10:04 AM



Written by J'koi at 09/28/2023 12:35 PM

**Attached Images:**





**1982 Nissan 280ZX**  
1N1CZ04SXCX626281  
Engine: L6, 2.8L; Turbo  
Plate:  
Odometer In: 67151  
Odometer Out: 67151

**Advisor: Reece**  
Technician: J'koi

**GRAND TOTAL: \$263.48**

**✓ PAID**

**SERVICES**

**1 PRE PURCHASE / SALE INSPECTION**

**SUBTOTAL: \$160.00**

**LABOR**

- COMPUTER DIAGNOSTIC
- ROAD TEST
- VISUAL INSPECTION OF UNDERCARRIAGE AND DRIVE TRAIN
- WRITTEN REPRT OF FINDINGS

**2 OIL SERVICE 5W-30 (FULL SYNTHETIC) + Basic Maintenance**

**SUBTOTAL: \$77.44**

**LABOR**

- Drain & Refill the Engine with Full Synthetic 5W-30 Motor Oil
- Remove & Replace Engine Oil Filter
- Top-off fluids (washer fluid, transmission, differential power steering, and engine coolant)
- Reset the Oil Level Indicator
- Reset the Service Indicator
- Calibrate tire pressure

**PARTS**

	<b>QTY</b>
TekStar Extended Performance DexOS	4.8
5W-30 Motor Oil	
Carquest Oil Filter	1.0

**HAZMATS & FEES**

	<b>QTY</b>
Disposal Fee	1.0

**3 ELEVATE - Digital Vehicle Inspection**

**SUBTOTAL: \$0.00**

**LABOR**

- Inspect the safety and performance components:



**Terms of Service:**

1. "YES, DO THIS WORK"

I hereby authorize the corresponding service to be done along with the necessary materials and documents such as "Waiver Of Liability" if present and required.

2. We understand that unexpected issues can arise, and we are committed to open communication with our valued customers. If our technicians encounter any unforeseen challenges during the service or repair process, we will promptly inform you of the situation and present a detailed plan to address the issue. Vehicles naturally age, and various parts can become more brittle or degraded over time. Our skilled technicians will exercise the utmost care and professionalism when working on your vehicle. However, due to factors such as the vehicle's age, condition, and prior maintenance history, there is a possibility that certain parts could break or experience increased fragility during the course of necessary service or repairs.

3. "YOU MAY DRIVE MY CAR ON PUBLIC ROADS"

The J.A.P. shop staff may operate my vehicle for the purpose of testing, inspection, and delivery.

4. "NO PAYMENT, NO KEYS"

An express lien is acknowledged on my vehicle to secure the amount of services thereto.

5. "ONLINE COMMUNICATION OK"

I welcome email from The JAP shop as a means of receiving copies of my estimate, work order, and invoice.

6. "OVERNIGHT PARKING"

On working vehicles, there would be \$45 charge per night on 3rd day after closing date listed on the invoice and/or \$170 per day after the diagnostic/inspection has been complete on inoperable vehicles.

7. "WARRANTY"

We provide 36 months 36,000 miles parts and labor warranty. Warranty does not apply to used or customer supplied parts.

8. "HERE'S MY SIGNATURE"

I endorse the attached digital image of my signature as equivalent to my written signature and as proof of my agreement to these five terms.

**GRAND TOTAL: \$263.48**

Shop Supplies: \$9.00

Sales Tax: \$17.04

✓ PAID

09/14/2023 12:03 PM

Paid by Credit Card - Visa: **\$263.48**

**Authorization:**

---




**INSPECTION REPORT**

**ELEVATE - Digital Vehicle Inspection**

<input checked="" type="checkbox"/> <b>Body &amp; Exterior</b>
<input checked="" type="checkbox"/> Inspect Dashboard Warning Indicators
<input checked="" type="checkbox"/> Perform Complete Visual Inspection of Engine Compartment: belts, hoses, wiring, 12v battery terminals
<input checked="" type="checkbox"/> Inspect Brake Fluid Level & Test
<input checked="" type="checkbox"/> Inspect Engine Oil Level and Condition
<input checked="" type="checkbox"/> Inspect Transmission Fluid Condition (it won't be inspected on sealed systems and flush is due based on manufacturer recommendations)
<input checked="" type="checkbox"/> Inspect Engine Coolant Level
<input checked="" type="checkbox"/> Inspect Power Steering Fluid Level
<input checked="" type="checkbox"/> Inspect Engine Air Filter
<input checked="" type="checkbox"/> Test 12V Battery
<input checked="" type="checkbox"/> Inspect and Top of Washer Fluid, Wiper Blades and Wiper Motor Operation
<input checked="" type="checkbox"/> <b>Inspect Drive Shaft Boots</b>
<input checked="" type="checkbox"/> Inspect Front & Rear Brake Rotors, Pads, Calipers, Hoses, Hardware
<input checked="" type="checkbox"/> Inspect tire Tread Wear/Depth
<input checked="" type="checkbox"/> Set Tire Pressures to Specification
<input checked="" type="checkbox"/> <b>Inspect Ball Joints &amp; Dust Covers</b>
<input checked="" type="checkbox"/> <b>Inspect Steering Linkage &amp; Boots</b>



**FINDINGS**



Written by J'koi at 09/14/2023 09:27 AM

**Body & Exterior**

Minot Rust on underbody

Written by J'koi at 09/14/2023 09:30 AM

**Inspect Brake Fluid Level & Test**

Full and clean

Written by J'koi at 09/14/2023 09:35 AM

**Perform Complete Visual Inspection of Engine Compartment: belts, hoses, wiring, 12v battery terminals**

Good

Written by J'koi at 09/14/2023 09:36 AM

**Inspect Engine Coolant Level**

Full and clean

Written by J'koi at 09/14/2023 09:37 AM

**Inspect Power Steering Fluid Level**

No leaks

Written by J'koi at 09/14/2023 09:37 AM





**Inspect Drive Shaft Boots**

Outer seals have a slow leak

Written by J'koi at 09/14/2023 09:40 AM

**Inspect Ball Joints & Dust Covers**

Ball joints

Written by J'koi at 09/14/2023 09:41 AM

**Inspect Steering Linkage & Boots**

Tie rod ends

Written by J'koi at 09/14/2023 09:41 AM

**Remove and Replace Tie Rod End     \$291.08 +tax**

**Remove & Replace: Ball Joint     \$564.58 +tax**

Written by Reece at 09/14/2023 11:02 AM

**Remove & Install Or Remove & Replace: Propeller Shaft,  
Remove & Install Or Remove & Replace: Propeller Shaft  
(Labor Only)     \$400.00 +tax**

**Remove & Replace: Oil Pan Gasket(Labor Only)  
\$440.00 +tax**

Written by Reece at 09/14/2023 11:04 AM

**Four Wheel Alignment     \$99.00 +tax**

Written by Reece at 09/14/2023 11:09 AM

Vehicle was test driven by two shop employees. Both of which boasted about the drivability of this vehicle. For the age this vehicle is in spectacular condition, of course at the mileage it will have some wear but in comparison to a lot of the ones we get in the shop, it is leagues above them. We've had fully rebuilt aftermarket front end suspensions come in and this car drives better than those. Interior is also in perfect condition with strong A/C, which is extremely rare on sports cars from this era. Considering the mileage, condition, age and dealership options on the vehicle this car is a one in a lifetime kind of car.

Personal Testimony: One of the test drivers is a manager at the shop, he owned one when he was 16/17. After the test drive he wanted to make an offer immediately. He stated "This vehicle drives like my brand new one back in 1983".

This vehicle will be a gift to anyone who is lucky enough to own it.

Written by Reece at 09/14/2023 11:59 AM

**Attached Images:**



